



Technical Service Bulletin

34 Oil leak from the ATF sump area

34 19 41 2050215/5 June 13, 2019. Supersedes Technical Service Bulletin Group 34 number 19-40 dated April 2, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad	2017	N000001 - N044921 Or A000001 - A089798	0CK, 0CL, and 0CJ Transmissions
A5	2017	All	0CK, 0CL, and 0CJ Transmissions
A5, A5 Cabriolet, and A5 Sportback	2018	000001 - 005035	0CK, 0CL, and 0CJ Transmissions
A6	2016	All	0CK, 0CL, and 0CJ Transmissions
A6	2017	000001 – 062073	0CK, 0CL, and 0CJ Transmissions
Q5	2018	000001 – 004987	0CK, 0CL, and 0CJ Transmissions

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised <i>Service</i> (Gasket for the oil pan added, ATF sump replacement removed) Revised <i>Required Parts and Tools</i> (Updated part required)
4	04/02/2019	Revised <i>Warranty</i> (Updated Labor Operations)
3	07/10/2018	Revised header data (Added models)

Customer statement:

- Oil leaking from the vehicle.

Workshop findings:

- Oil leak found in the ATF sump area.

Technical Background

Not applicable.



Technical Service Bulletin

Production Solution

Improved assembly procedure.

Service

If the reported oil leak appears to be from the ATF sump area proceed with diagnosis and repair as follows:

1. Take photos of the actual condition and attach to the Repair Order.
2. Retighten the ATF sump bolts with a torque of 5 Nm. Make sure to follow the correct tightening sequence (Figure 1).




Figure 1. Tightening sequence.

3. Clean the sump and transmission thoroughly with brake clean and make sure the transmission and sump are dry before proceeding.



Technical Service Bulletin

4. Apply oil leak detection spray (Part # G 001 900 A1 or a locally available talcum-based oil leak detection spray equivalent) to the sealing area of the sump, ATF cooler, drain plug, and the case half seam (Figure 2).



Figure 2: Transmission with oil leak detection spray applied.

5. Test drive the vehicle and reassess the oil leak after the test drive.
6. If there is no further leaking the condition is repaired. Use Claim Warranty Table 1 for this repair.



Technical Service Bulletin



Tip: If there are drips after the test drive as shown (Figure 3) you should be able to determine if the leak is from the ATF sump gasket or if the leak is from elsewhere. Make sure to check for leaks above the sump gasket. Check the seam of the transmission case split and the weep hole of the double seal (Figure 4). Both of these leaks can be confused for an ATF sump gasket leak.



Figure 3. Oil leak.



Technical Service Bulletin



Figure 4. Double seal weep hole location.



Tip: If the ATF sump gasket has been diagnosed to be leaking after all the above checks, replace the ATF sump gasket according to the Repair Manual and recheck for leaks. Use Warranty Table 2 if the ATF sump gasket is replaced. If the repair manual is followed using the special tools, the required wheel alignment should not be necessary.



Note:

If the oil leak is not from the ATF sump gasket please open an Audi Technical Assistance contact with the pictures of the leak attached to the ticket and contact Audi Technical Assistance for repair authorization.



Technical Service Bulletin

Warranty


Warranty Table 1 (Retightening bolts repaired oil leak)

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	3756		
Damage Code:	0050		
Labor Operations:	Noise dampening pan remove + reinstall	1082 9999	50 TU
	Retighten Mechatronics Cover Bolts	3460 1399	10 TU
	Clean gearbox and apply talcum spray	3435 2999	30 TU
	Check gearbox housing for leaks (incl. photos)	3435 0199	40 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 40 TU)
	Road test prior to service the procedure	0121 0002	10 TU
	Road test after service the procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2050215/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Warranty Table 2 (ATF Sump Gasket replacement repaired oil leak)

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	3460		
Damage Code:	0010		



Technical Service Bulletin

Labor Operations:	All Models:		
	Noise dampening pan remove + reinstall	1082 9999	50 TU
	Retighten Mechatronics Cover Bolts	3460 1399	10 TU
	Clean gearbox and apply talcum spray	3435 2999	30 TU
	Check gearbox housing for leaks (incl. photos)	3435 0199	40 TU
	A4, A5, and Q5:		
	Remove and install the mechatronic unit cover (Replace Gasket)	3460 1900	See SRT
	A6:		
	Remove and install mechatronic unit cover (Replace Gasket)	3460 1903	See SRT
	Diagnostic Time:	GFF	0150 0000
Road test prior to the service procedure		0121 0002	10 TU
Road test after the service procedure		0121 0004	10 TU
Claim Comment:	As per TSB #2050215/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Special Tools for Mechatronics Cover Replacement:

Tool Number	Tool Description
T10552	Rear Axle Support



Technical Service Bulletin

T40043	Ball Joint Puller
T40335	Strut
T40334	Locating Pin
T40386	Mount
VAS6931	Engine and Gearbox Jack or equivalent
VAG1331	Torque Wrench 1331 5-50Nm or equivalent

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.

Part Number	Part Description	Quantity
G001900A1	Oil leak detection spray (or equivalent)	Shop Supply
G055529A2	Dual Clutch Gearbox Oil (ATF)	3.5 max
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Parts below are only used if the Transmission Oil Sump requires replacement:

Part Number	Part Description	Quantity
0CK321371	Gasket for the oil pan	01 (If needed)
0CK325107F	Tube	01

Additional Information

All parts and service references provided in this TSB (2050215) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.