

## IMPORTANT INFORMATION

Please inform and provide a copy of this document to every person in your dealership with campaign-related responsibilities, including Service, Parts and Accounting personnel. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety. If you have questions regarding this or any other campaign, please call (800) 741-2919.



# Safety Recall Circular

**REVISED** Code:  
JN/JN00

**Subject: 1998-2004 Audi A6 Avant and Sedan and  
2001-2005 Audi allroad quattro equipped with Halogen Low Beam  
Rerouting of the Headlight Switch Wiring Harness with Installation of  
a Jumper Wiring Harness**

January 2007

### Revision Summary

An additional step has been added to the work procedure for affected allroad vehicles. The headlight range control module (55) requires a coding change in order to prevent the creation of a fault code caused by the installation of the relay harness. **NEW** information appears in red in the work procedure.

### Problem Description

Audi has found evidence of a potential defect in the wiring circuit on the subject vehicles that could lead to overheating or fire if certain connector pins in the headlight switch connector come into contact with each other.

### Corrective Action

The headlight switch wiring harness will be rerouted by installing a jumper wiring harness.

### VIN Ranges of Affected Vehicles (USA Only)

1998-2004 Audi A6 Sedan and Avant and

2001 Audi allroad quattro

WAU \_\_\_ 4B\_WN026592 – WAU \_\_\_ 4B\_4N104386

2001-2005 Audi allroad quattro

WA1 \_\_\_ 4B\_2N028925 – WA1 \_\_\_ 4B\_5N024719

USA specification halogen low beam headlight vehicles  
ONLY

Date of Production: August 1997 – June 2005

*NOTE: Check ElsaWeb on the day of repair to verify vehicle eligibility and attach the screen print to the repair order. This is the only valid campaign inquiry and verification source. Some vehicles may be involved in an additional action(s); any additional work can be done while the vehicle is in for this action.*

### Allocation Report of Affected Vehicles

In the Service Manager's Package, dealers with affected vehicles received a report containing the complete VIN, customer name and address data. The list was based on the vehicles in their AOR. Dealers did not receive a report if they have no affected vehicles.

*NOTE: The allocation report contains owner names and addresses obtained from Motor Vehicle Registration Records. By law, this data may only be used for recall purposes. Use for any other reason may be a violation of law in many states/provinces. Accordingly, you must limit the use of this report.*

### Parts Information and Allocation

Due to limited parts availability, on or about December 18, 2006, you received a small first allocation of parts. If you have exhausted your allocated parts and you require additional parts for vehicles affected by this safety recall, but have exceeded your Upper Order Limit, please submit your requests for additional parts via email to [upperorderlimits@audi.com](mailto:upperorderlimits@audi.com). Be sure to include the affected VINs with your order. Prior to submitting your request, ensure that each vehicle has the JN code open in ElsaWeb. Your order will be reviewed and processed accordingly.

### Owner Notification Mailing

On or about December 15, 2006 Audi began notifying all known owners of affected vehicles by first-class mail. A sample copy of the owner letter is enclosed.

**CONTINUE TO NEXT PAGE**