

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64

Version: Release 19.6.2

www.Ross-Tech.com

Dealer/Shop Name:

Workshop Code: 000 00000

Diagnostic Trouble Code Report

Monday,30,March,2020,23:43:26:64934

VIN: WAUMFAFH9FN000848 License Plate:

Mileage: Repair Order:

Control Module Part Number: 8F0 959 255 HW: 8F0 959 255

Component and/or Version: VSG-AUDI-B8 H12 0190

Software Coding: 030000

Work Shop Code: WSC 02391 785 00200

ASAM Dataset: EV\_ElectRoofContr 001008 (AU48)

VCID: 71BFD394D126C0EF36B-8024

2 Faults Found:

0020 - Convertible Top Compartment Switch; Left

B1181 29 [137] - Signal Implausible

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 1

Reset counter: 70

Mileage: 28120 km

Date: 2020.03.30

Time: 16:41:15

0021 - Convertible Top Compartment Switch; Right

B1182 29 [137] - Signal Implausible

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 1

Reset counter: 70

Mileage: 28120 km

Date: 2020.03.30

Time: 16:41:15