

VCDS-Lite Version: Release 1.1  
Sunday, 15 July 2012, 20:01:40:26597

Chassis Type: 8E - Audi A4 B6/B7  
Scan: 01,02,03,08,09,0F,11,15,16,17,18,36,37,45,46,55,56,57,65,67,69,75,76,77

-----  
Address 01: Engine    Labels: Redir Fail!  
Controller: 8E0 909 518 F  
Component: 1.8L R4/5VT    G    0001  
Coding: 0016751  
Shop #: WSC 63351  
VCID: 3319FB2A123B  
No Faults Found  
or DTCs not supported by controller  
or a communication error occurred

-----  
Address 02: Auto Trans    Labels: 01V-927-156.LBL  
Controller: 8E0 927 156 P  
Component: AG5 01V 1.8I5VT USA 1213  
Coding: 0001002  
Shop #: WSC 22129  
VCID: 3B09D30A3A6B  
1 Fault Found:  
18265 - Load Signal: Error Message from ECU  
      P1857 - 003 - Mechanical Failure - Intermittent

-----  
Address 03: ABS Brakes    Labels: 8E0-614-517.LBL  
Controller: 8E0 614 517 A  
Component: ABS/ESP allrad    1726  
Coding: 04277  
Shop #: WSC 22129  
VCID: 263F127ED1E9  
2 Faults Found:  
01119 - Gear Recognition Signal  
      35-10 - - - Intermittent  
18265 - Load Signal: Error Message from ECU  
      P1857 - 35-10 - - - Intermittent

-----  
Address 08: Auto HVAC    Labels: 8E0-820-043.LBL  
Controller: 8E0 820 043 AG  
Component: A4 Klimaautomat 1424  
Coding: 00000  
Shop #: WSC 00000

VCID: 66BF527E1169

No Faults Found

or DTCs not supported by controller  
or a communication error occurred

---

Address 09: Cent. Elect. Labels: 8E0-907-279-8E2.LBL

Controller: 8E0 907 279 E

Component: int. Lastmodul KAN 0305

Coding: 00004

Shop #: WSC 91429

VCID: 341BF8361735

No Faults Found

or DTCs not supported by controller  
or a communication error occurred

---

Address 15: Airbags Labels: 8E0-959-655-84.LBL

Controller: 8E0 959 655 A

Component: Airbag 8.4E 4000

Coding: 0010607

Shop #: WSC 63351

VCID: 351DC5321C4F

3 Faults Found:

00589 - Airbag Igniter 1; Passenger Side (N131)

002 - Lower Limit Exceeded

00654 - Seat Belt Tensioner Igniter; Driver Side (N153)

001 - Upper Limit Exceeded

01217 - Side Airbag Igniter; Driver Side (N199)

001 - Upper Limit Exceeded - Intermittent

---

Address 16: Steering wheel Labels: 8E0-953-549.LBL

Controller: 8E0 953 549 L

Component: Lenksäulenmodul 0308

Coding: 01121

Shop #: WSC 22110

VCID: 3C0BD0163F65

1 Fault Found:

01044 - Control Module Incorrectly Coded

35-00 - -

---

Address 17: Instruments Labels: 8E0-920-9xx-8E2.LBL

Controller: 8E0 920 950 H

Component: KOMBI+WEGFAHRS. RB4 D26

Coding: 01331

Shop #: WSC 91429

VCID: 2E2FEA5EF919

WAULC68E92A209772 AUZ6Z0A0347753

2 Faults Found:

00562 - Sensor for Oil Level/Temperature (G266)

30-00 - Open or Short to Plus

00562 - Sensor for Oil Level/Temperature (G266)

27-00 - Implausible Signal

---

Address 45: Inter. Monitor Labels: 8E0-951-177.LBL

Controller: 8E0 951 177

Component: Innenraumueberw. 0604

Coding: 00001

Shop #: WSC 00000

VCID: EBA9A34A8A8B

1 Fault Found:

01463 - Alarm triggered by Sensor for anti-theft alarm System

81-00 - Open

---

Address 46: Central Conv. Labels: 8E0-959-433-MAX.LBL

Controller: 8E0 959 433 T

Component: Komfortgerät T5B 0617

Coding: 11788

Shop #: WSC 63351

VCID: 42F7AEEE5D81

6 Faults Found:

01581 - Incorrect Component Detected

35-00 - -

01370 - Alarm triggered by Interior Monitoring

35-00 - -

01559 - Drivers Door

61-00 - Won't De-Safe

01560 - Passenger Door

61-00 - Won't De-Safe

01561 - Left Rear Door

61-00 - Won't De-Safe

01562 - Right Rear Door

61-00 - Won't De-Safe

---

Address 56: Radio Labels: 8E0-035-1xx-56.LBL

Controller: 8E0 035 195 A

Component: symphony II NP2 0007

Coding: 00001

Shop #: WSC 00000

VCID: 253D1572ACEF

1 Fault Found:

00878 - Connection to Speaker Front Left  
36-10 - Open Circuit - Intermittent

End -----