Date	Mileage	Parts	Labor	Туре	Sub-Type	Explanation
6/26/2013	131,438	\$287.97	\$262.50	Service	Interval	120k service
		\$0.00	\$225.00	Service		Default??
4/2/2013	127,812	\$951.60	\$0.00	Repair	Replace	4 TPMS sensors
		\$548.70	\$192.50	Repair	Replace	Front brake discs and pads
		\$0.00	\$125.00	Service		Mount and balance five tires
		\$84.80	\$161.00	Repair	Replace	Serpentine belt
		\$131.35	\$384.00	Repair		Wiring repair to brake pad harness
1/12/2013	125,141	\$4.74	\$9.00	Repair	Replace	Light bulb
12/7/2012	124,109	\$17.00	\$0.00	Service	Replace	Windshield wipers
11/27/2012	123,775	\$700.90	\$172.80	Repair	Replace	Throttle Body
		\$1,166.00	\$51.00	Repair	Diagnose	Check Engine light & ESP Light
		\$0.00	\$537.60	Repair	Replace	ABS Unit
		\$0.00	\$51.00	Repair	Diagnose	ABS warning light
		\$1,245.00	\$640.00	Repair	Replace	Catalytic Converter
		\$141.62	\$364.80	Repair	Replace	Brake Caliper
9/26/2012	122,172	\$0.00	\$109.00	Repair	Diagnose	Malfunction Indicator Lamp
		\$0.00	\$128.00	Repair		Electrical service to multiple points
		\$13.60	\$12.95	Repair	Replace	Remote batteries
		\$0.00	\$69.00	Repair		Removed frozen hardware
9/4/2012	121,672	\$65.20	\$34.95	Service		Oil & Filter change
		\$0.00	\$69.00	Repair	Diagnose	System charging / noise / leak
3/29/2012	116,741	\$50.20	\$34.95	Service		Oil & Filter Change
		\$0.00	\$69.00	Repair		Tested individual tire pressure
		\$0.00	\$100.00	Service		Mount and balance 4 new tires
		\$14.00	\$79.00	Service		Brake Flush
		\$3.00	\$9.00	Repair	Replace	Right rear license plate bulb
6/6/2011	109,027	\$59.00	\$216.00	Service	Interval	110k Service
		\$24.00	\$0.00	Service	Replace	Windshield wipers
		\$280.00	\$153.00	Repair	Replace	Rear brake discs and pads
12/17/2010	106,146	\$254.92	\$25.00	Service		Mount and balance one tire (replace flat)
4/16/2010	101,978	\$7.20	\$100.00	Service		Mount and balance 4 new tires
		\$1,060.00	\$100.00	Purchase		Four (4) new tires
1/9/2010	100,275	\$205.00	\$0.00	Warranty	Replace	Tire Warranty replacement

		\$3.60	\$25.00	Service		Mount and balance one tire (replace flat)
7/10/2009	94,667	\$31.90	\$29.95	Service		Oil & Filter Change
		\$35.84	\$76.80	Repair	Replace	Coolant Temp. Sensor
		\$0.00	\$99.00	Repair	Diagnose	Malfunction Indicator Lamp
		\$31.25	\$211.20	Repair	Replace	Right Rear Diff Seal
12/10/2008	90,558	\$435.00	\$212.50	Repair	Replace	Front brake discs and pads
		\$985.36	\$100.00	Purchase		Four (4) new tires
		\$11.34	\$57.50	Service		Inspect and modify??
		\$815.20	\$412.50	Repair	Replace	Radiator
		\$1,009.29	\$887.50	Repair	Replace	Timing Belt / Water Pump / Rollers
		\$0.00	\$93.75	Repair		Repired threads on front brake caliper
8/26/2008	87,319	\$1,139.62	\$250.00	Repair	Replace	Left Catalytic converter
		\$0.00	\$49.00	Repair	Diagnose	System charging / noise / leak
		\$461.66	\$34.50	Repair	Replace	Electric mirror housing
		\$27.38	\$218.50	Repair	Replace	Front propshaft flange oil seal
7/30/2008	86,738	\$36.32	\$186.00	Service	Interval	90k service
2/14/2008	81,469	\$0.00	\$122.00	Repair	Replace	Failed vacuum line
11/19/2007	79,872	\$0.00	\$35.00	Repair	Diagnose	Shimmy felt through steering wheel
		\$0.00	\$19.95	Service		Rotate tires
9/17/2007	76,686	\$1,032.29	\$145.60	Repair	Replace	Right Catalytic converter
		\$0.00	\$22.40	Repair	Diagnose	Read Data Memory
		\$0.00	\$56.00	Repair	Diagnose	Readiness Code
		\$464.77	\$145.60	Repair	Replace	Altrernator
		\$370.75	\$588.95	Service	Interval	80k Service
		\$107.30	\$415.00	Repair	Replace	Both outer CV boots
		\$226.68	\$153.00		Replace	Rear brake discs and pads
		\$137.06	\$33.60		Replace	TPMS sensor
		\$0.00	\$22.40	Repair		Wheel remove and reinstall - See above
2/19/2007	70,796	\$35.70	\$129.95	Service	Interval	70k Service
		\$0.00	\$19.95	Service		Rotate tires
		\$11.66	\$0.00	Service	Replace	Wiper Inserts
		\$18.48	\$80.00	Service		Brake Flush
10/23/2006	63,975	\$180.00	\$39.95	Repair	Replace	Battery
		\$400.50	\$67.20	Repair	Replace	3 TPMS Sensors

		\$0.00	\$44.80	Repair		Remove and re-install 2 wheels - see above
		\$0.00	\$56.00			Radio Fault code
7/18/2006	61,131	\$160.04	\$192.25		Interval	60k Service
		\$1,266.40	\$100.00	Purchase		Four (4) new tires
		\$0.00	\$149.95	Service		Alignment
5/24/2006	57,054	\$0.00	\$50.00	Service		Mount and balance 2 tires
		\$0.00	\$128.70	Repair		check and adjust hand-brake
9/8/2005	49,980	\$43.45	\$159.50	Service	Interval	50k service
		\$410.01	\$99.00	Service		Resurface Front Brake pads / rotors
		\$1,391.95	\$143.00	Repair	Replace	Right Catalytic converter
		\$0.00	\$71.50	Repair		Diagnosis - see above
		\$163.32	\$77.00	Repair	Replace	Right rear brake disc
		\$0.00	\$22.00	Repair		Wheel remove and reinstall - See above
		\$0.00	\$99.00	Repair		Removed Front Brake Disc
		\$0.00	\$22.00	Repair		Wheel remove and reinstall - See above
9/23/2005	46,982	\$0.00	\$19.95	Service		Rotate tires
		\$0.00	\$159.95	Service		Alignment
		\$139.31	\$77.00	Repair	Replace	Left tie rod
6/30/2005	43,340	\$166.66	\$99.00	Repair		Brake pad front removed and reinstalled
		\$0.00	\$22.00	Repair		Wheel remove and reinstall - See above
		\$0.00	\$110.00	Repair		Tracking Electrical failure
6/9/2005	42,732	\$162.59	\$58.50	Repair	Replace	Front fog light hit by rock
		\$58.00	\$71.50	Repair		Technical diagnosis - see below
		\$0.00	\$110.00		Replace	Corroded connector ends
5/9/2005	42,224	\$307.75	\$181.50	Service	Interval	40k service
		\$0.00	\$88.00			Checked and cleaned brake pad connections
		\$7.74		Service		Brake flush
		\$11.44		Service	Replace	Wiper Inserts
12/7/2004	35,102	\$0.00	\$99.00			Check Front and Rear alignment
		\$0.00	\$22.00			Adjust rear toe
		\$0.00	\$33.00			Adjust front camber
		\$0.00	\$33.00	-		Adjust front toe
		\$92.97	\$82.50		Replace	Sensor
		\$0.00	\$110.00	Repair		Technical diagnosis - see above

11/30/2004	32,213	\$295.90	\$99.00	Repair		Fron brake disc removed and replaced
		\$0.00	\$22.00	Repair		Wheel remove and reinstall - See above
		\$0.00	\$110.00	Repair		Technical diagnosis - see above
9/29/2004	30,313	\$99.65	\$33.00	Repair	Replace	Nav Switch
11/17/2003	18,822	\$155.34	\$147.90	Service	Interval	20k service

Total \$20,257.27 \$12,805.80