

LAUNCH

Vehicle Diagnostic Report

Test Time:2021-03-12 08:20:27
 VCI Serial Number:985491509900
 Shop Name:RGMotorsport
 Address:
 Telephone:011 792 8352
 Email :steveng@rgmotorsport.com
 Model:Audi
 Version:V28.55
 01 Engine Control Module 1
 U111300 Function Limitation Due To Received Malfunction Value passive/abio genesis
 U111300 Function Limitation Due To Received Malfunction Value passive/abio genesis
 P305400 Starter Does Not Turn-Mechanically Blocked Or Electrical Malfunction passive/abio genesis
 P010400 Mass Or Volume Air Flow Sensor 'A' Circuit Intermittent passive/abio genesis
 P056800 Cruise Control Set Signal passive/abio genesis
 U140A00 Terminal 30-Open Circuit passive/abio genesis
 P068A00 ECM/PCM Power Relay De-Energized Performance - Too Early passive/abio genesis
 03 Brakes 1
 U140000 Function Restriction-due To Insufficient Voltage passive/abio genesis
 U111300 Function Limitation Due To Received Malfunction Value passive/abio genesis
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 C101816 Return Pump - Voltage Too Low passive/abio genesis
 C10A416 Low Pressure Sensor Power Supply - Voltage Too Low passive/abio genesis
 05 Kessy
 00955 Key 1 Lower Limit Exceeded
 00956 Key 2 Lower Limit Exceeded
 00446 Function Limitation Due To Insufficient Voltage Lower Limit Exceeded
 01330 Comfort System Central Control Module Check DTC Memory
 08 Air Conditioning
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 U111300 Function Limitation Due To Received Malfunction Value active/static
 U140000 Function Restriction-due To Insufficient Voltage passive/abio genesis
 U111100 Function Limitation Due To Missing Message passive/abio genesis
 U111300 Function Limitation Due To Received Malfunction Value active/static
 U111300 Function Limitation Due To Received Malfunction Value active/static
 U111300 Function Limitation Due To Received Malfunction Value active/static
 09 Central Electrics
 00978 Left Low Beam Headlamp Bulb Electrical Fault in Circuit
 00532 Supply Voltage Lower Limit Exceeded
 01520 Rain/light Recognition Sensor No Signal/Communication
 01229 Humidity Sensor, A/C System No Signal/Communication
 01229 Humidity Sensor, A/C System Defective
 10 Parking Assistance 2
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 U140000 Function Restriction-due To Insufficient Voltage passive/abio genesis
 15 Airbag
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 16 Steering Column Electronics
 00446 Function Limitation Due To Insufficient Voltage Lower Limit Exceeded
 00532 Supply Voltage Lower Limit Exceeded

17 Dash Board
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 19 Gateway
 C10AFF2 Voltage Stabilizer - Stage 1 Voltage Supply Failed To Reach Lower Limit passive/abio genesis
 C10AFF6 Voltage Stabilizer - Stage 2 Voltage Supply Failed To Reach Lower Limit passive/abio genesis
 U104900 Optical Data Bus - Open Circuit passive/abio genesis
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 U140600 Static Current - Too High active/static
 U140B00 Energy Management Active passive/abio genesis
 28 Climate Control Unit Rear
 B10C707 Button In Operating Unit - Mechanical Malfunction passive/abio genesis
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 U140000 Function Restriction-due To Insufficient Voltage passive/abio genesis
 36 Seat Adjustment Driver Side
 00532 Supply Voltage Lower Limit Exceeded
 42 Door Electronics Driver Side
 02115 Lock Unit For Central Locking Implausible Signal
 02123 Door Warning Light / Entry Light Electrical Fault in Circuit
 00532 Supply Voltage Lower Limit Exceeded
 44 Steering Assistance
 U140A00 Terminal 30-Open Circuit passive/abio genesis
 46 Central Module Comfort System
 02615 Locking Fuel Tank Cap Open or Short to Ground
 02616 Unlocking Fuel Tank Cap Open or Short to Ground
 00216 EC Mirror Signal Fade In Electrical Fault in Circuit
 00532 Supply Voltage Lower Limit Exceeded
 03610 Voltage Supply For Roof Electronics Control Module Lower Limit Exceeded
 03128 Sunroof Tilt Button 1 Electrical Fault in Circuit
 00204 Sunroof Button Electrical Fault in Circuit
 52 Door Electronics Passenger Side
 00532 Supply Voltage Lower Limit Exceeded
 53 Parking Brake
 U101100 Supply Voltage - Voltage Too Low passive/abio genesis
 55 Headlight Regulation
 U140000 Function Restriction-due To Insufficient Voltage passive/abio genesis
 56 Radio
 00446 Function Limitation Due To Insufficient Voltage Lower Limit Exceeded
 5F Information Control Unit 1
 02067 Optical Data Bus Unauthorized Awakening Request
 00532 Supply Voltage Lower Limit Exceeded
 03367 Voltage Supply Of Display Unit Lower Limit Exceeded
 62 Door Electronics Rear Left
 00532 Supply Voltage Lower Limit Exceeded
 72 Door Electronics Rear Right
 00532 Supply Voltage Lower Limit Exceeded
 02 Transmission Control Module
 3B Sensor Electronics

LAUNCH

Vehicle Diagnostic Report

Test Time:2021-03-12 08:28:47
 VCI Serial Number:985491509900
 Shop Name:RGMotorsport
 Address:
 Telephone:011 792 8352
 Email :steveng@rgmotorsport.com
 Model:Audi
 Version:V28.55
 03128 Sunroof Tilt Button 1 Electrical Fault in Circuit
 00204 Sunroof Button Electrical Fault in Circuit

ROB GREEN AUTO SERVIC

2021-03-12 08:40:09
 TT:VX528 AB:100 VC:5.0.7

M: 000000007313927
 U: 00005872

CUSTOMER COPY

N: 6113 TSN: 6158
 Credit
 P: 400974*****0999
 UTI: 7F5FE926-67BF-4E5
 2-A575-1F4B94F2C758
 D: 21/03/12 T: 08:40:21

AID: A0000000031010
 TSI: F800
 TVR: 0000000000
 AC: FAGC20184FC00B02
 Visa Card

Approved

Purchase	R509.00
TOTAL	R509.00