

VAG-COM
Windows Based VAG/VAS Emulator
Version: Release 704.1
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000

Diagnostic Trouble Code Report
Wednesday, 02, March, 2011, 21:49:56:26365

VIN: License Plate:
Mileage: Repair Order:

Control Module Part Number: 03G 906 016 HS
Component and/or Version: R4 2,0L EDC G000SG 9673
Software Coding: 0000072
Work Shop Code: WSC 02324

2 Faults Found:

001032 - EGR Potentiometer (G212): Signal too High
P0408 - 000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000
Fault Priority: 2
Fault Frequency: 60
Mileage: 121670 km
Time Indication: 0
Date: 2011.03.02
Time: 09:18:23

Freeze Frame:

RPM: 2667 /min
Speed: 83.0 km/h
Load: 19.2 %
Lambda: -9.8 %
Mass Air / Rev.: 365.0 mg/str
Mass Air / Rev.: 460.0 mg/str
Bin. Bits: 00000000

001027 - EGR Valve (N18): Malfunction
P0403 - 000 - -

Freeze Frame:

Fault Status: 01110000
Fault Priority: 2
Fault Frequency: 72
Mileage: 121678 km
Time Indication: 0
Date: 2011.03.02
Time: 09:26:11

Freeze Frame:

RPM: 1029 /min
Speed: 24.0 km/h
Duty Cycle: 84.4 %
Voltage: 13.98 V
Mass Air / Rev.: 515.0 mg/str
Duty Cycle: 4.4 %
Bin. Bits: 00000000

Readiness: 1 1 0 0 0