

L12056A  
 Reg in  
 Box



# Vehicle claims history report

## Vehicle Damage

VIN	Year	Make	Model
WAUZL54B71N155721	2001	AUDI	A6

## Your Search Results

<b>Status:</b>	<p><b>Normal</b>                  If a vehicle does not have a status of rebuilt, salvage, non-repairable, or altered, it is considered to have a normal status. "Normal" is simply a term used for the purposes of vehicle registration.</p> <p>A normal status does not mean the vehicle has never been damaged or is in good mechanical condition. Vehicle status alone does not fully describe a vehicle's mechanical condition or damage history.</p>
<b>Vehicle Imported: (from outside B.C.)</b>	<b>NO</b>

## ICBC Claim History

Claim Date	Type of Claim	Amount Paid	Nature of Payment
24JAN2002	COLLISION	3439.35	REPAIRS

Taxes are not included in the amounts paid

## Statements of Limitation

### Vehicle Status:

B.C.-registered vehicles may have a status of normal, rebuilt, salvage, altered, or non-repairable.

**Please note:** Vehicle status alone does not fully describe a vehicle's mechanical condition or damage history.

Vehicle status records are obtained from the B.C. vehicle registry at the date and time of a VIN search. Any changes to a vehicle's status after that date will change the information shown.

The status may not represent the vehicle accurately for a number of reasons, including any of the following:

- A written off vehicle has not been reported to the B.C. vehicle registry.
- A vehicle wrecker or recycler has not reported a vehicle that has been decommissioned.
- A vehicle with major damage was repaired by its owner.
- An insurer denied a claim, or the owner did not follow through with a claim.
- A vehicle was recently written off, but the registry has not been updated yet.
- A vehicle imported to B.C. (either from Canada or the U.S.) had an incorrect status in the jurisdiction it came from.

### Vehicle Claims History:

This is a report of vehicle damage and repairs paid by ICBC at the date and time this report is issued. Any claim payments and adjustments made after that date will change the information shown.

10  
LEXUS OF KELOWNA  
2767 HIGHWAY 97 NORTH  
KELOWNA, BC V1X4J8

JEFF GRKINICH

15

06/04/12

LEIS10148

132,612 silver/

L12056A

01/AUDI/A6/A6

132,612

W A U Z L 5 4 B 7 1 N 1 5 5 7 2 1

05/09/12

250-448-0990

MO: 132612

TOTALS-----

CONTROL#	ACCOUNT NUMBER	AMOUNT..
	6I	210.00
	6I	112.06
L12056A	157B	51.50
	6I	113.50
	6I	88.50
	6I	103.24
	6I	568.00

TOTAL LABOR....	876.99
TOTAL PARTS....	363.31
TOTAL SUBLET...	0.00
TOTAL G.O.G....	6.50
TOTAL MISC.CHG.	0.00
TOTAL MISC.DISC	0.00
TOTAL TAX.....	0.00

**TOTAL INVOICE \$ 1246.80**

APPROVED BY SIGNATURE \_\_\_\_\_

*DONE!*

10  
LEXUS OF KELOWNA  
2767 HIGHWAY 97 NORTH  
KELOWNA, BC V1X4J8

JEFF GRKINICH

15

06/04/12

LEIS10148

132,612

silver/

L12056A

01/AUDI/A6/A6

132,612

W A U Z L 5 4 B 7 1 N 1 5 5 7 2 1

05/09/12

250-448-0990

MO: 132612

JOB# 1 CHARGES-----

LABOR-----

J# 1 70LEZZ01	USED CAR INSPECTION	HOURS: 2.00	TECH(S):22	210.00
TECH#	DATE	START	FINISH	ACT TIME
22	05/26/12	9.10	15.90	0.00
		TOTAL TECH TIME		0.00 0.00

CONDITION: PERFORM USED VEHICLE INSPECTION  
CORRECTION: COMPLETED

JOB# 1 TOTALS-----  
LABOR 210.00

JOB# 1 JOURNAL PREFIX LEIS JOB# 1 TOTAL 210.00

JOB# 2 CHARGES-----

LABOR-----

J# 2 01LE1A001	OIL AND FILTER	HOURS: 0.50	TECH(S):22	52.50
TECH#	DATE	START	FINISH	ACT TIME
22	06/04/12	0.00	0.00	0.00
		TOTAL TECH TIME		0.00 0.00

CONDITION: PERFORM OIL AND FILTER SERVICE  
CORRECTION: COMPLETED

PARTS-----	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
	8	5W30	5W30 OIL	4.17	33.36
	1	L792655	OIL FILTER	22.95	22.95
	TOTAL - PARTS				56.31

G.O.G. & SUPPLIES-----

1.0	ENVIRO WASTE DISPOSAL	@	3.250	/UNIT	
TOTAL - GOG					3.25

JOB# 2 TOTALS-----  
LABOR 52.50  
PARTS 56.31  
G.O.G. 3.25

JOB# 2 JOURNAL PREFIX LEIS JOB# 2 TOTAL 112.06

JOB# 3 CHARGES-----

LABOR-----

J# 3 71LEZZ05	NITROGEN FILL	HOURS: 0.30	TECH(S):22	31.50
TECH#	DATE	START	FINISH	ACT TIME
22	06/04/12	0.00	0.00	0.00
		TOTAL TECH TIME		0.00 0.00

CONDITION: CONNECT NITRO MACHINE, INTIALIZE TO INFLATE TIRES AND SET  
TIRE PRESSURES TO VEHICLE SPECIFICATIONS  
CORRECTION: FILLED ALL TIRES TO VEHICLE SPECIFICATIONS WITH NITROGEN

10  
LEXUS OF KELOWNA  
2767 HIGHWAY 97 NORTH  
KELOWNA, BC V1X4J8

JEFF GRKINICH

15

06/04/12

LEIS10148

132,612 silver/

L12056A

01/AUDI/A6/A6

132,612

W A U Z L 5 4 B 7 1 N 1 5 5 7 2 1

05/09/12

250-448-0990

MO: 132612

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	550-001	NITRO KIT	20.00	20.00
				TOTAL - PARTS	20.00

JOB# 3 TOTALS-----

LABOR	31.50
PARTS	20.00

JOB# 4 CHARGES-----

JOB# 3 JOURNAL PREFIX LEIS	JOB# 3 TOTAL	51.50
----------------------------	--------------	-------

LABOR-----

J# 4+19LEZZ00	DIAGNOSE AND REPORT HOURS: 0.30	TECH(S):22	31.50
TECH# 22	DATE 06/04/12	START 0.00	FINISH 0.00
	ACT 0.00	TIME 0.00	DESCRIPTION ENTERED IN INVOICING
TOTAL TECH TIME		0.00	0.00

CONDITION: HOOD NOT STAYING UP ON IT'S OWN  
CORRECTION: REPLACED HOOD STRUT

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	TAU59311	HOOD STRUT	82.00	82.00
				TOTAL - PARTS	82.00

JOB# 4 TOTALS-----

LABOR	31.50
PARTS	82.00

JOB# 5 CHARGES-----

JOB# 4 JOURNAL PREFIX LEIS	JOB# 4 TOTAL	113.50
----------------------------	--------------	--------

LABOR-----

J# 5+19LEZZ01	INTERIOR TRIM (B) HOURS: 0.30	TECH(S):22	31.50
TECH# 22	DATE 06/04/12	START 0.00	FINISH 0.00
	ACT 0.00	TIME 0.00	DESCRIPTION ENTERED IN INVOICING
TOTAL TECH TIME		0.00	0.00

CONDITION: COVER/SURROUND FOR OUTER MIRROR SWITCH IS BROKEN/CORRODED  
CORRECTION: REPLACED MIRROR SWITCH COVER

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
	1	AU59366	SWITCH COVER	57.00	57.00
				TOTAL - PARTS	57.00

JOB# 5 TOTALS-----

LABOR	31.50
PARTS	57.00

JOB# 6 CHARGES-----

JOB# 5 JOURNAL PREFIX LEIS	JOB# 5 TOTAL	88.50
----------------------------	--------------	-------

LABOR-----

10  
LEXUS OF KELOWNA  
2767 HIGHWAY 97 NORTH  
KELOWNA, BC V1X4J8

JEFF GRKINICH

15

06/04/12

LEIS10148

132,612

silver/

L12056A

01/AUDI/A6/A6

132,612

W A U Z L 5 4 B 7 1 N 1 5 5 7 2 1

05/09/12

250-448-0990

MO: 132612

JOB# 6 CHARGES-----

LABOR-----		INSTALL 4 TIRES		HOURS:		TECH(S):22		
TECH#	DATE	START	FINISH	ACT	TIME	DESCRIPTION		
J# 6+09LEZZ17						ENTERED IN INVOICING		99.99
22	06/04/12	0.00	0.00	0.00				
TOTAL TECH TIME				0.00	0.00			

CONDITION: MOUNT & BALANCE 4 TIRES  
CAUSE: VIBRATION AT 80 KPH  
CORRECTION: REBALANCED ALL 4 TIRES  
ROADTESTED - ALL OKAY

G.O.G. & SUPPLIES-----

1.0	ENVIRO WASTE DISPOSAL	@	3.250	/UNIT	3.25
1.0		@		/UNIT	0.00
TOTAL - GOG					3.25

JOB# 6 TOTALS-----

LABOR 99.99  
G.O.G. 3.25

JOB# 6 JOURNAL PREFIX LEIS JOB# 6 TOTAL 103.24

JOB# 7 CHARGES-----

LABOR-----		MISC FRONT SUSPEN		HOURS: 4.00		TECH(S):22		
TECH#	DATE	START	FINISH	ACT	TIME	DESCRIPTION		
J# 7+16LEZZ06						ENTERED IN INVOICING		420.00
22	06/04/12	0.00	0.00	0.00				
TOTAL TECH TIME				0.00	0.00			

CONDITION: BOTH FRONT UPPER CONTROL ARM BUSHINGS ARE WORN  
CORRECTION: REPLACED BOTH FRONT UPPER CONTROL ARM BUSHINGS

PARTS-----	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
	4	AU59366	BUSHINGS	37.00	148.00
TOTAL - PARTS					148.00

JOB# 7 TOTALS-----

LABOR 420.00  
PARTS 148.00

JOB# 7 JOURNAL PREFIX LEIS JOB# 7 TOTAL 568.00

# Used Car & Truck - Mechanical Inspection

Stock # 42056A Yr. 01 V.I.N. 1N155721 Make Audi Model A6  
 Miles \_\_\_\_\_ Kilometers 132612 Date May 9 R.O. # \_\_\_\_\_ Color Silver

## INSTRUCTIONS:

OOP \_\_\_\_\_  NITRO \_\_\_\_\_ P.O. # \_\_\_\_\_  
 Detail Complete \_\_\_\_\_  L.O.F. \_\_\_\_\_ Time In \_\_\_\_\_  
 Inspection & Report \_\_\_\_\_  Cut Extra Keys \_\_\_\_\_ Time Out \_\_\_\_\_  
 Cut & Polish \_\_\_\_\_ Warranty \_\_\_\_\_  
 Compression Test \_\_\_\_\_  
 \_\_\_\_\_  \_\_\_\_\_ Signature \_\_\_\_\_  
 \_\_\_\_\_  \_\_\_\_\_

## Road Test: Technician, please be sure to mark in each box:

, "OK", or  (Needs Attention), or  (Minor Attention Needed)

Engine  Transmission  Steering  Brakes  
 Tires  Speedo  Odometer (M  or K )  Cruise

## INSPECTION:

### Engine

Oil Leaks  
 Noise Level

### Cooling System

Pressure Test  
 Leaks  
 Hoses  
 Cooling Fan  
 Water Pump  
 Radiator Cap  
 Anti-Freeze Strength Record 410

### Axle

Oil Condition & Level  
 Axle Seals  
 Pinion Seal  
 Drive Shaft

### Transmission - Automatic

Leaks  
 Oil Condition  
 Cooler Lines

### Transmission - Standard

Leaks & Oil Level  
 Clutch Free Play

### 4 x 4 System

Leaks  
 Oil Level  
 Operation

### Brakes mm

Linings: Left Front 8 Right Front 8  
 Linings: Left Rear 8 Right Rear 5

Rotors  Drums  Fluid Leaks   
 Hoses  Cyls  Calipers   
 Master Cylinder  Parking Brake  ABS Operation

### Tire Depth Remaining

Left Front 8 Right Front 8 Left Rear 9 Right Rear 9  
 Spare  Jack

### Suspension / Steering

Linkage  Ball Joints   
 Box/Rack  Springs   
 Shocks  Fluid Leaks   
 Torsion Bar Mounts

### Electrical

All Lights  Horn   
 Wipers & Washer  Heater   
 Air Conditioning  Accessories   
 Battery Condition  Rear Defog

### General

Exhaust System  Belts   
 Filters  Fuel Leaks   
 Frame  Seat Belt   
 SRS Light

Technician's Signature [Signature] Date May 25 2012